2022-01-17

Release notes GLB/TWIN firmware version 1.3.5

- Version 1.3.5 support both GLB and TWIN wallboxes

1. **Added firmware features**
   1.1. Support for Western Automation DC current monitoring
   1.2. Support for new energy meter GARO GMI3D-LP and ISKRA IE38MD

2. **Bug fixes**
   2.1. PDF Energy reports could fail for other non-Swedish time zones
   2.2. DLM wakeup signal disabled when car is fully charged
   2.3. Temperature limits for charging under extreme conditions adjusted
   2.4. Energy meter could interfere with RFID-reader under certain conditions
   2.5. Twinbox in slavemode could end up in deactivated mode under certain circumstances